Mo/Rh kV measurements

Place the active sensor area centered and 6 cm from the chest wall side.

Place this 2 mm Al filter on the sensor. Be sure to cover the active sensor area.

Recommended generator setting: ≥ 100 mAs.

